## Make check payable to **ED SYLVIS**

**Foundation Review** 326 N. Ogden Dr. Los Angeles, CA 90036

Statement date

16-Jan-15

Invoice date

16-Jan-15

**Total for Review** 

200.00

	Description	Check	Date	Item
\$200.00	Inspection Fee	·	16-Jan-15	Foundation
\$200.00	Ralance due			

## Thank you for Choosing the Very Best!!


Please note inspection fee is due on site at time of inspection.

Inspection fee is payable in cash or check.

Reports can not be released until inspection fee is paid.

We always have and always will GIVE YOU MORE than we promise!!

Should a contract be negotiated with in 60 days the fee is a credit to the contract cost.



The information below was found on the following address:

#### 326 N OGDEN DR

Parcei	Profile	Report:
		•

1

Permit Information found:

4

- 326-326 1/2 N OGDEN DR 90036
- 326 N OGDEN DR 90036
- 326-328 N OGDEN DR #326 1/2 90036
- **326-328 N OGDEN DR 90036**

Application/Permit #	PC/Job #	Туре	Status	Work Description
06041 - 10000 - 03351	X06LA02635	Electrical	Permit Finaled 12/8/2006	200AMP (3-GANG) METER SERVICE. TO INCLUDE REWIRE THROUGHOUT. (UNITS #326, #326 1/2, AND #328)
06042 - 70000 - 03390	X06SL00954	Plumbing	Permit Finaled 2/1/2007	REPLACE & COPPER RE-PIPE PLBG. FIXTURES, ADD 1 BATH AND CLOTHESWASHER, & INSTALL E.Q SHUT OFF VALVE FOR UNITS #326 & 328 OF THE TRIPLEX. "the work is deemed NOT to affect the habitability of a rental unit"

Code Enforcement Information:

0

# The City of Los Angeles Department of Building and Safety

The information below was found on the following address:

#### 326 N OGDEN DR

Parcel Profile Report:

1

Permit Information found:

4

## 326-326 1/2 N OGDEN DR 90036

Application/Permit #	PC/Job #	Туре	Status	Work Description
06014 - 30000 - 02100	B06WL01111	Bldg- Alter/Repair	Permit Finaled 2/5/2007	replace 6'x21'-8' upper floor deck

## 326 N OGDEN DR 90036

## 326-328 N OGDEN DR #326 1/2 90036

Application/Permit #	PC/Job #	Туре	Status	Work Description
06042 - 70000 - 03376	X06SL00950	Plumbing	Permit Finaled 5/24/2006	REPLACE & COPPER RE-PIPE PLBG. FIXTURES AND INSTALL WTR. HTR. & E.Q SHUT OFF VALVE FOR UNIT #326 1/2 OF THE TRIPLEX. "the work is deemed NOT to affect the habitability of a rental unit"

## **326-328 N OGDEN DR 90036**

Application/Permit #	PC/Job #	Туре	Status	Work Description
06041 - 10000 - 03351	X06LA02635	Electrical	Permit Finaled 12/8/2006	200AMP (3-GANG) METER SERVICE. TO INCLUDE REWIRE THROUGHOUT. (UNITS #326, #326 1/2, AND #328)
06042 - 70000 - 03390	X06SL00954	Plumbing	Permit Finaled 2/1/2007	REPLACE & COPPER RE-PIPE PLBG. FIXTURES, ADD 1 BATH AND CLOTHESWASHER, & INSTALL E.Q SHUT OFF VALVE FOR UNITS #326 & 328 OF THE TRIPLEX. "the work is deemed NOT to affect the habitability of a rental unit"

## The City of Los Angeles Department of Building and Safety

The information below was found on the following address:

## 326 N OGDEN DR

Parcel Profile Report:

1

Permit Information found:

4

### **326-326 1/2 N OGDEN DR 90036**

Application/Permit #	PC/Job #	Туре	Status	Work Description
06014 - 30000 - 02100	B06WL01111	Bldg- Alter/Repair	Permit Finaled 2/5/2007	replace 6'x21'-8' upper floor deck

#### **326 N OGDEN DR 90036**

Application/Permit #	PC/Job #	Туре	Status	Work Description
05016 - 20000 - 23380	B05VN22523	Bldg- Alter/Repair	Permit Finaled 2/2/2007	NON-STRUCTURAL INTERIOR REMODEL TO UNIT #1 - CONVERT DINING ROOM TO KITCHEN & CONVERT KITCHEN & BREAKFAST AREA TO A BEDROOM with bath(AREA OF WORK IS APPROX. 400 S.F. TOTAL)
06014 - 30001 - 02100	B06WL01111	Bldg- Alter/Repair	Permit Finaled 2/5/2007	correct address, use on pcis 06014-30000-02100
06016 - 30000 - 12089	X06WL03925	Bldg- Alter/Repair	Application Submittal 6/22/2006	correct address, occupancy and use on pcis 06014-30000- 02100
06016 - 30000 - 10307	X06WL03385	Bldg- Alter/Repair	Permit Finaled 2/5/2007	CHANGE OUT 8 WINDOWS (SAME SIZE & LOCATION) RESIDENTIAL BATHROOM REMODEL- REPAIR/REPLACE ONLY- NO CHANGES IN WALLS OR OPENINGS. DRYWALL PLASTER PATCH & PAINT.

## 326-328 N OGDEN DR #326 1/2 90036

326-328 N OGDEN DR 90036

Code Enforcement Information:

0